

Teile-Nr./ Part-No.:

0791 911700

## 1 Komponenten des Bausatzes

Der Teilesatz **0911 597544** besteht aus folgenden Komponenten.

- 1 x Winkel 0911 562760
- 2 x Druckluftregler 9710 400050
- 2 x Zylinderschraube 9202 002077
- 2 x Scheibe 9330 000087
- 1 x Ventil 9710 061200
- 2 x Ventil 0999 220764
- 1 x Y-Steckanschluss 0999 240408
- 4 x Verschr. WI-E 9790 201000
- 4 x Kabelbinder 9840 121002
- 4m Schlauch-PUR 9731 005004
- 2 x gerade Steckverbindung 0999 240404
- Anschlußplan




#### Vorsicht Verletzungsgefahr!

Hauptschalter ausschalten!

Bausätze nur bei ausgeschalteter Nähanlage anbauen.

### 2 Anbau



Ausgabe/Edition: 06.2010

Änderungsindex Rev. index: **00.0** 

Printed in Germany


Blatt: von Sheet: 1 from 8



Teile-Nr./ Part-No.:

0791 911700

- Den vormontierten Winkel (mit Manometern) 3 mit den Schrauben 4 an die N\u00e4hanlage schrauben (siehe Abbildung).
- Abdeckung 5 entfernen.
- Ventil 6 montieren (Platz Nr. 8).
- Schläuche verlegen und anschließen (siehe Anschlußplan).



3



### STO C 2.5 'NSF

### ST

6

5



Teile-Nr./ Part-No.:

0791 911700

## 3 Aktivierung des Bausatzes

Der Bausatz verminderter Druck ist eine optionale Baugruppe und muss noch aktiviert werden.

Vorgehensweise:

siehe Bedienanleitung Kapitel 7.7.4.

Ausgabe/Edition: 06.2010

Änderungsindex Rev. index: **00.0** 


Printed in Germany

Blatt: von Sheet: 3 from 8



Teile-Nr./ Part-No.:

0791 911700



Ausgabe/Edition: 06.2010

Anschlußplan für Bausatz "verminderter Klammerdruck"

Änderungsindex Rev. index: **00.0** 

Printed in Germany

Blatt: von Sheet: 4 from 8



Teile-Nr./ Part-No.:

0791 911700

### 1 Kit components

The kit 0911 597544 consists of the following components:

- 1 x Angle iron 0911 562760
- 2 x Compressed air regulator 9710 400050
- 2 x Cylinder head screw 9202 002077
- 2 x Washer 9330 000087
- 1 x Valve 9710 061200
- 2 x Valve 0999 220764
- 1 x wye connector 0999 240408
- 4 x Connection WI-E 9790 201000
- 4 x Cable tie 9840 121002
- 4 m Hose PUR 9731 005004
- 2 x Connector 0999 240404
- Connection diagram




#### Caution: Risk of injury!

Turn off the main switch!

Proceed with the fitting procedure of the kit with the sewing unit switched off!

## 2 Mounting



Ausgabe/Edition: 06.2010

Änderungsindex Rev. index: **00.0** 

Printed in Germany


Blatt: von Sheet: 5 from 8



Teile-Nr./ Part-No.:

0791 911700

- Screw on the pre-mounted angle iron (with manometers) 3 using the screws 4 to the sewing unit (see figure).
- Remove the cover 5.
- Mount the valve 6 (position number 8).
- Lay and connect the hoses (see connection diagram).



3



*y* 

## \$10 C 2.5 NBR ## \$10000 PMS 5-780- ## \$12000 PMS 5-780- ## \$13200 PMS

6

5



Teile-Nr./ Part-No.:

0791 911700

### 3 Kit activation

The kit "Reduced Pressure" is an optional equipment and has yet to be activated.

#### **Proceeding:**

check operating instructions chapter 7.7.4.

Ausgabe/Edition: 06.2010

Änderungsindex Rev. index: **00.0** 


Printed in Germany

Blatt: von Sheet: 7 from 8



Teile-Nr./ Part-No.:

0791 911700



Ausgabe/Edition: 06.2010

Änderungsindex Rev. index: **00.0** 

Printed in Germany

Blatt: von Sheet: 8 from 8