


Conversion of old spare parts numbers

Actual Format: 4 digits/ blank/ 6 digits/ blank/ additional digits:

0 5 5 7 0 0 0 6 0 2 A
 ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■ ■



Examples:

New Parts Number

Old Parts Number

0216 000005

216 5

0238 005104

238 5104

0002 000450 690

002 450 690

N005 000001

N005 1

0001 002300 110

001 2300 110

0265 008906 A

265 8906 A

0467 150094

K467 150094